





Toku TCH-2,3,4 Chipping Hammer

| Index | Tamco | Kent | Description | List Price |
|-------|-----------|--------|---------------------------------|------------|
| 1-2 | Y10430010 | K04193 | Cylinder for TCH-2 | \$187.99 |
| 1-3 | Y10450010 | K04194 | Cylinder for TCH-3 | \$187.99 |
| 1-4 | Y10470010 | K04195 | Cylinder for TCH-4 | \$187.99 |
| 2 | Y10430020 | K04196 | Flange Bumper Ring | \$6.69 |
| 3-2 | Y10430030 | K04273 | Piston for TCH-2 | \$22.77 |
| 3-3 | Y10450030 | K04274 | Piston for TCH-3 | \$22.77 |
| 3-4 | Y10470030 | K04275 | Piston for TCH-4 | \$22.77 |
| 4 | Y10103080 | K04197 | Spring Pin 6 x 24 | \$2.15 |
| 5 | Y10430050 | K04198 | Bumper Valve Seat | \$5.56 |
| 6 | Y10430060 | K04199 | Valve Spacer | \$35.31 |
| 7 | Y10212150 | K04229 | Valve | \$6.96 |
| 9 | Y10430090 | K04231 | Hex Socket Plug GDL 1/8 -27 | \$1.34 |
| 10 | Y10430100 | K04235 | Handle | \$203.30 |
| 11 | Y10601110 | K04236 | Trigger | \$20.33 |
| 12 | Y10430120 | K04237 | Throttle Valve Bushing | \$11.72 |
| 13 | Y10430130 | K04238 | O-Ring AS568-203 | \$1.87 |
| 14 | Y10430140 | K04239 | Throttle Valve | \$20.44 |
| 15 | Y10430150 | K04241 | Throttle Valve Spring | \$3.16 |
| 16 | Y10430160 | K04242 | O-Ring G-25 | \$0.96 |
| 17 | Y10430170 | K04246 | Air Inlet | \$12.95 |
| 18 | Y10430180 | K04243 | Flange | \$71.74 |
| 19 | Y10430190 | K04244 | Handle Hex Bolt 11T (M12 x 80) | \$2.51 |
| 19B | Y1043019B | K04256 | Spring Washer (25 x 12.2 x 1.5) | \$0.96 |
| 20 | Y10430200 | K04247 | Bumper Washer | \$3.32 |
| 22 | Y10430220 | K04215 | Handle Bolt Spacer | \$6.26 |
| 23 | Y10430230 | K04248 | Handle Bolt Nut M12 | \$2.19 |
| 25 | Y10430250 | K04249 | Exhaust | \$32.10 |
| 28 | T25119002 | K04173 | Body Retainer | \$36.74 |
| 34 | Y10212300 | K02428 | Lock Coil Spring | \$1.32 |
| 44H | Y1021224H | K04170 | Shank Bushing (Hex) | \$16.69 |
| 44R | Y1021224R | K04165 | Shank Bushing (Round) | \$16.69 |